Sacramento Archetype Study – ISWP Water Body Categorization

Study Area	Water Body	ISWP Category
Biggs	Lateral K	C1
	C Main Drain	C1
	Cherokee Canal	C1
Colusa	Unnamed Tributary	Not listed in original report (C1)
	New Ditch	Not listed in original report (C1)
	Powell Slough	Not listed in original report
		(C3 downstream of Hwy 20)
Live Oak	Lateral 1	C1
	Lateral 2	C1
	East Interceptor Canal	C1
	Wadsworth Canal	C1
Willows	Ag Drain C	C3 outside of refuge, B1 inside refuge
	Logan Creek	C3 outside of refuge, B1 inside refuge
	Hunter Creek	C3 outside of refuge, B1 inside refuge